

Play Area Safety Inspection Report - Operational Oakham Town Council - Princess Avenue Fenced In Play Area February 2021

The inspection was carried out by Lewis Baines - RPII Certified Operational Playground Inspector OP3798

Multiplay Unit





Manufacturer - Wicksteed

Installation Date - 2004

Observations - Some trip hazards evident around perimeter. These should be topped up to eliminate.



Toddler Swing



Manufacturer - Wicksteed

Installation Date - 2012

Observations - Extremely muddy and slippery underfoot. Not easy to use.



Sign Your Name Panel



Manufacturer - Wicksteed
Installation Date - 2012
Observations - None
Risk - Low



Mushroom Stools & Talking Flowers



Manufacturer - Wicksteed
Installation Date - 2012
Observations - None
Risk - Very low

Play Car



Manufacturer - Wicksteed
Installation date - 2012
Observations - None
Risk - Very low



Horse See Saw



Manufacturer - Wicksteed

Installation date - 2012

Observations - None

Risk - Low

Roundabout



Manufacturer - Wicksteed

Installation date - 2012

Observations - None



Trim Trail - Steel











Manufacturer - Wicksteed

Installation Date - 2012

Observations - None



Play Area Safety Inspection Report - Operational Oakham Town Council - Princess Avenue Main Play Area February 2021

The inspection was carried out by Lewis Baines - RPII Certified Operational Playground Inspector OP3798

Supernova



Manufacturer - Kompan

Installation Date - Unknown

Observations - Areas of base works under surfacing have subsided and causing surface to move. This will result in surface splitting and becoming unsafe. Recommend replacement surfacing and base works as required.



Galaxy Unit



Manufacturer - Kompan


Installation Date - 2002

Observations - Some items missing (presumed removed due to damage). Very boggy under foot.



Rotating Bowls





Manufacturer - Kompan
Installation Date - 2001
Observations - None
Risk - Low



Balance Swing



Manufacturer - Kompan

Installation Date - 2010

Observations - None

Risk - Low

Skate Unit



Manufacturer - Kompan

Installation Date - 2010

Observations - One platform showing signs of damage. Monitor



Spinning Pole



Manufacturer - Kompan
Installation date - 2010
Observations - None
Risk - Low



5 Bay Swing



Manufacturer - Kompan

Installation date - 2010

Observations - None



Single Point Swing



Manufacturer - Kompan

Installation Date - Unknown

Observations - New bearing, basket seat and chains

Risk Level - Low



Air Walker



Manufacturer - Ashlands Fitness

Installation date - Unknown

Observations - Signs of wear and corrosion. Monitor for further deterioration



Cross Trainer



Manufacturer - Ashlands Fitness

Installation Date - Unknown

Observations - Signs of wear and corrosion. Monitor for further deterioration



Air Skier



Manufacturer - Ashlands Fitness

Installation date - Unknown

Observations - Signs of wear and corrosion. Monitor for further deterioration



Horse Rider



Manufacturer - Ashlands Fitness

Installation date - Unknown

Observations - Signs of wear and corrosion. Monitor for further deterioration