

# Play Area Safety Inspection Report - Operational

Oakham Town Council - Willow Crescent Play Area

# February 2021

The inspection was carried out by Lewis Baines - RPII Certified Operational Playground Inspector OP3798

#### 1 Bay 2 Flat Seat Swing



Manufacturer - Kompan

Installation Date - 2015

Observations - Missing caps on crossbar. Recommend replacement



#### 1 Bay 2 Cradle Seat Swing



Manufacturer - Wicksteed

Installation Date - Unknown

Observations - Rubber tiles are prone to getting extremely slippery throughout Autumn / Winter. Recommend monitoring during weekly checks.



#### 1 Bay 1 Seat Swing



Manufacturer - SMP

Installation Date - Unknown

Observations - Rubber tiles are prone to getting extremely slippery throughout Autumn / Winter. Recommend monitoring during weekly checks.



### Forest Play Panel



Manufacturer - Kompan

Installation Date - 2010

Observations - Most items seem to have been removed, leaving this play panel without much function. Further research found that replacing the items was cost prohibitive. Recommend removal as item offers very little play value.



## Control Play Panel



Manufacturer - Kompan

Installation Date - Unknown

Observations - None



### Spinning Pole



Manufacturer - Kompan
Installation date - 2015
Observations - None
Risk - Low



### 4 Way Springer



Manufacturer - Kompan

Installation date - 2015

Observations - None

Risk - Low

#### Multi Play Unit





Installation date - 2015

Observations - None

Risk - Low

#### See Saw





Manufacturer - Wicksteed

Installation Date - Unknown

Observations - Rubber tiles are prone to getting extremely slippery throughout Autumn / Winter. Recommend monitoring during weekly checks.

Risk - Low

## Stepping Posts





Installation date - 2015

Observations - None

Risk - Low

## Ladybird Springer





Installation date - 2015

Observations - None

Risk - Low

#### Pull Up Bars





Installation Date - 2015

Observations - None

Risk - Very low





Installation Date - 2015

Observations - Monitor grass mats for separation leading to trip hazards.

Risk - Low

### Trim Trail





Manufacturer - Unknown

Installation Date - 2006

Observations - The trim trail is showing signs of wear and tear to be expected with timber equipment of its age. There is strimmer damage and general splits and cracks but the most noteworthy is the slipperiness of the timber. Recommend this is monitored with weekly checks.

Risk - Low

#### Entrance Gate





Manufacturer - Unknown

Installation Date - Unknown

Observations - Gate closes too quickly. Recommend gate closes between 4-8 seconds