



Play Area Safety Inspection Report - Operational
Oakham Town Council - Princess Avenue Fenced In Play Area
August 2020

The inspection was carried out by Lewis Baines - RPII Certified Operational Playground Inspector OP3798

Multiplay Unit



Manufacturer - Wicksteed

Installation Date - 2004

Observations - Wetpour safety surface shrinkage - scheduled for repair by Playscape

Risk - Low



Toddler Swing



Manufacturer - Wicksteed

Installation Date - 2012

Observations - Satisfactory

Risk - Low



Sign Your Name Panel



Manufacturer - Wicksteed

Installation Date - 2012

Observations - Post cap removed. On scheduled maintenance list for Playscape.

Risk - Low

Mushroom Stools



Ridlington Park Farm, Holygate Road, Ridlington, Rutland LE15 9AR 01572 759411

www.playscapeplaygrounds.co.uk sales@playscapeplaygrounds.co.uk

Registered In England Number 9717529 VAT 238 8112 03



Manufacturer - Wicksteed

Installation Date - 2012

Observations - None

Risk - Very low

Talking Flower



Manufacturer - Wicksteed

Installation Date - 2012

Observations - None

Risk - Very low



Play Car



Manufacturer - Wicksteed

Installation date - 2012

Observations - None

Risk - Very low



Horse See Saw



Manufacturer - Wicksteed

Installation date - 2012

Observations - None

Risk - Low

Roundabout



Manufacturer - Wicksteed

Ridlington Park Farm, Holygate Road, Ridlington, Rutland LE15 9AR 01572 759411

www.playscapeplaygrounds.co.uk sales@playscapeplaygrounds.co.uk

Registered In England Number 9717529 VAT 238 8112 03



Installation date - 2012

Observations - None

Risk - Low

Trim Trail - Steel



Manufacturer - Wicksteed

Installation Date - 2012

Observations - None

Risk - Low



Gates / Benches/ Litter Bins / Fencing

All satisfactory