




## Play Area Safety Inspection Report - Operational

Oakham Town Council - Cutts Close Play Area

February 2021

The inspection was carried out by Lewis Baines - RPII Certified Operational Playground Inspector OP3798

### 1 Bay 2 Cradle Seat Swing



Manufacturer - Wicksteed

Installation Date - Unknown

Observations - None

Risk - Low



### Supernova



Manufacturer - Kompan

Installation Date - 2010

Observations - Grass mat safety surface separating. Monitor for further deterioration and trip hazards

Risk - Low



Surfer



Manufacturer - Kompan

Installation Date - 2010

Observations - None

Risk - Low





### Spinning Pole



Manufacturer - Kompan

Installation Date - 2010

Observations - Some play in the bearing. Monitor for further deterioration and allow for maintenance.

Risk - Low



1 Bay 2 Seat Cradle Swing



Manufacturer - Wicksteed

Installation Date - Unknown

Observations - Rubber tiles are prone to being extremely slippery in Autumn and Winter.  
Monitor this during weekly checks

Risk - Low



1 Bay 2 Seat Flat Swing



Manufacturer - Wicksteed

Installation date - Unknown

Observations - None

Risk - Low





1 Bay 2 Seat Flat Swing



Manufacturer - Wicksteed

Installation date - Unknown

Observations - None

Risk - Low



1 Bay 2 Seat Flat Swing



Manufacturer - Wicksteed

Installation date - Unknown

Observations - None

Risk - Low





Under 5's Entrance Gate



Manufacturer - Prosafe

Installation Date - Unknown

Observations - None

Risk - Low



Toddler Multi-Play



Manufacturer - Park Leisure

Installation date - Unknown

Observations - None

Risk - Low





## Talk Tubes



Manufacturer - Park Leisure

Installation date - Unknown

Observations - None

Risk - Low



## Mushrooms



Manufacturer - Park Leisure

Installation Date - Unknown

Observations - None

Risk - Very low





#### 4 Way Springer



Manufacturer - Park Leisure

Installation Date - Unknown

Observations - Area under unit is dirty with wetpour surfacing showing signs of separation. Recommend cleaning of wetpour and monitor separation.

Risk - Low



## Rubber Steps



Manufacturer - Park Leisure

Installation Date - Unknown

Observations - None

Risk - Low





## Roundabout



Manufacturer - Park Leisure

Installation Date - Unknown

Observations - Rubber wetpour safety surface showing signs of separation. Bearings showing signs of wear and will require replacement.

Risk - Low



See-Saw



Manufacturer - Park Leisure

Installation Date - Unknown

Observations - None

Risk - Low





## Wobble Boards



Manufacturer - Park Leisure

Installation Date - Unknown

Observations - None

Risk - Low



### Junior Multi-Play



Manufacturer - Park Leisure

Installation Date - Unknown

Observations - Rope net showing signs of wear - recommend replacement.

Risk - Medium

