



Play Area Safety Inspection Report - Operational

Oakham Town Council - Princess Avenue Main Play Area

August 2020

The inspection was carried out by Lewis Baines - RPII Certified Operational Playground Inspector OP3798

Supernova



Manufacturer - Kompan

Installation Date - Unknown

Observations - None

Risk - Low



Galaxy Unit



Manufacturer - Kompan

Installation Date - 20002

Observations - Some items missing (presumed removed due to damage).

Risk - Low



Rotating Bowls



Manufacturer - Kompan

Installation Date - 201

Observations - None

Risk - Low

Balance Swing



Manufacturer - Kompan

Installation Date - 2010

Observations - None

Ridlington Park Farm, Holygate Road, Ridlington, Rutland LE15 9AR 01572 759411

www.playscapeplaygrounds.co.uk sales@playscapeplaygrounds.co.uk

Registered In England Number 9717529 VAT 238 8112 03



Risk - Low

Skate Unit



Manufacturer - Kompan

Installation Date - 2010

Observations - One platform showing signs of damage. Monitor

Risk - Low

Spinning Pole





Manufacturer - Kompan

Installation date - 2010

Observations - None

Risk - Low

5 Bay Swing



Manufacturer - Kompan

Installation date - 2010

Observations - Some surface deterioration. Scheduled for maintenance

Risk - Low



Air Walker



Manufacturer - Ashlands Fitness

Installation date - Unknown

Observations - Signs of wear and corrosion. Monitor for further deterioration

Risk - Low

Cross Trainer



Manufacturer - Ashlands Fitness

Ridlington Park Farm, Holygate Road, Ridlington, Rutland LE15 9AR 01572 759411

www.playscapeplaygrounds.co.uk sales@playscapeplaygrounds.co.uk

Registered In England Number 9717529 VAT 238 8112 03



Installation Date - Unknown

Observations - Signs of wear and corrosion. Monitor for further deterioration

Risk - Low

Air Skier



Manufacturer - Ashlands Fitness

Installation date - Unknown

Observations - Signs of wear and corrosion. Monitor for further deterioration

Risk - Low



Horse Rider



Manufacturer - Ashlands Fitness

Installation date - Unknown

Observations - Signs of wear and corrosion. Monitor for further deterioration

Risk - Low